

# Oil Field Environmental Incident Summary

**Incident:** 20140507112156 **Date/Time of Notice:** 05/07/2014 11:21

**Responsible Party:** Murex Petroleum Corporation

**Well Operator:** MUREX PETROLEUM CORPORATION

**Well Name:** MOUSE RIVER PARK UNIT

**Field Name:** MOUSE RIVER PARK

**Well File #:**

**Date Incident:** 5/7/2014 **Time Incident:** 09:17 **Facility ID Number:** 404271-01

**County:** RENVILLE **Twp:** 162 **Rng:** 86 **Sec:** 13 **Qtr:**

**Location Description:**

**Submitted By:** Lacey Placek

**Received By:**

**Contact Person:** Shannon Holter  
363 N. Sam Houston Pkwy. E.  
Suite 200  
HOUSTON, TX 77060

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Fire

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	1	Barrels	1	Barrels		

**Description of Other Released Contaminant:**

1/2 oil, 1/2 brine leaked into dike from treater.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

N/A

**Areal Extent:**

***Potential Environmental Impacts:***

N/A

***Action Taken or Planned:***

Fire Department was called, fire was put out.

Vac truck arrived and sucked up fluids in the dike and pushed back down tank.

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 5/7/2014      ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Fire in treater. Released liquids remained inside the diking, according to the report. NDIC retains oversight.